

10/505343




FIG 1




FIG 2

10/505343

FIG 3










FIG 4a





10/505343

FIG 5a




FIG 5c





FIG 5b








FIG 8a




FIG 8b




FIG. 9




FIG. 10

10/505343




FIG. 11A

- 1) EXTREME LEFT POSITION:
NO FLOW THROUGH HEATER
CIRCUIT AND
NO FLOW THROUGH RADIATOR
CIRCUIT.




FIG. 11B

- 2) INTERMEDIATE POSITION:
FLOW THROUGH HEATER
CIRCUIT,
NO FLOW THROUGH RADIATOR
CIRCUIT.




FIG. 11C

- 3) EXTREME RIGHT POSITION:
NO FLOW THROUGH HEATER
CIRCUIT,
FLOW THROUGH RADIATOR
CIRCUIT.

10/505343

FIG 12

